

Case Study //

222 Exhibition Street, Melbourne

An industry-first predictive maintenance (PdM) regime has reduced asset failure, improved tenant comfort and delivered significant energy savings within a 28-year old commercial office building in the heart of Melbourne's theatre district.

Project Summary

Reduction in Energy Consumption:	11.5%
Improvement in NABERS Rating:	4 stars
Reduction in Temperature Complaints:	68%

Predictive maintenance improves the effectiveness of maintenance by evaluating the condition of the HVAC plant through periodic and continuous condition monitoring in order to direct maintenance activities, ensuring the building's HVAC achieves peak performance on a continual basis.

Built in the late 1980s, the 29-storey post-modern tower at 222 Exhibition Street in Melbourne's CBD was designed by architects Denton Corker Marshall who won the Royal Australian Institute of Architects (RAIA) Merit Award following its completion in 1989.

Offering over 30,000m² NLA (net lettable area) and basement car park accommodating more than 500 vehicles, the majority of the building is tenanted by WorkSafe Victoria.

After being purchased by LaSalle Investment Management in 2015, Knight Frank was appointed as facility manager and given the task of improving the building's systems and performance.

Knight Frank awarded Airmaster and partner analytics provider BUENO the opportunity to implement an industry-first predictive maintenance program across the building in mid-2016.

Although analytics, condition monitoring, controls and mechanical services have been utilised in commercial buildings before, until now they had never been operationally integrated in a commercial office building prior to the implementation at 222 Exhibition Street.

⁶⁶ The challenge was to make mechanical services and controls maintenance more effective in order to reduce asset failure, increase tenant comfort, increase equipment uptime and provide energy savings "

- Matthew Graham, Senior Facilities Manager at Knight Frank.

By mid-2017, despite a 13% increase in occupancy rate, electrical energy consumption had fallen by 11.5% and tenant comfort complaints reduced by 68%.

This has been achieved solely through the predictive maintenance program – no upgrades, BMS strategy changes or capital works have been undertaken.

Predicting failures

In contrast to traditional maintenance - where an asset and/or component is attended to on a scheduled-calendar basis - predictive maintenance is designed to provide maintenance to assets and associated components at the most cost-effective point in time while maintaining reliability and ensuring peak performance.

This requires the ability to identify the potential of an asset or component to fail by using an analytics platform. By analysing the large amounts of data generated by the BMS, the platform continually identifies faults and inefficiencies in the operation and condition of the buildings HVAC.

Airmaster and BUENO are then able to direct technicians via Bonfire & Airmaster MobileTEC notifications to diagnose and manage repairs proactively. Facility Manager's are also notified of the event, but are not required to intervene.

Some of the issues identified by BUENO's analytics platform included faulty VAV damperactuators, AHU air volume damper/actuators, temperature sensors, differential pressure sensors and associated pitot tubes, and supply air static pressure anomalies.

"There has been fewer complaints from tenants, and any potential issues for tenants are intercepted and resolved proactively," said Graham.

"Comparing the statistics on call rates to the Knight Frank facility response centre since the predictive regime was put in place to the same period the year before shows, that temperature and airflow related complaints have fallen by 68% – from 71 work orders to 23 - resulting in a cost avoidance of \$16,742."

For the occupants of 222 Exhibition St, the implementation of predictive maintenance has ensured that comfortable conditions are continually achieved; making the building's leased space more attractive.

Vibration Analysis

The use of vibration analysis is vitally important to the predictive maintenance program. Vibration analysis continually measures the condition of various rotating equipment.

Airmaster and BUENO have used the results of vibration analysis data to create a workflow display that further streamlines and reports on issues and outcomes.

Siereno D) Saet			
Harm - 🗁 222 Condition 20 -	🔁 222 Decision (B. M. Berliner) - 🔛 Vitration Anatom 🎂			n.
	the second states in some distance di some		Diversion A set of	tion O human 14 halfson
	Autologont Summany Use Day Companies Mask to date 1	Summary Thermal Contort Issue Summary Issue Tracking Spark Summa	any Vibratian Analysis	
	Wheating Analysis Separity Read down	Frank Instally		We Ownerfaile
	Contract Analysis of the state	Loging: Device and Loging and COMPLAND WHILE Code (Condense Were Party 3 Marco)		- 14 · · · ·
		Lovel 1 MAN Supposed 2008/0 AMD 78/385 (Scher 21) polynami Water Party 3: Party	01	here's
		Land 1 MMC Represent COMPO Dellar 2/Contenuer Water Purg 3, Monor		
	Coulda Dileven	Land 1 MMC Equipment CONTR Date Providence Meter Party 3, Party Land 1 MMC Equipment CONTLASIC WORK Index Information Meter Area. 1, Nature		Contra Cont
		Loss 11950 Epigenetic COPPLANT 19789 Date: Infontance Marc 3-Party		1 to 10
		Laws 1 MMC Equipment CORT Only 1 Contenue Water Purp 3 Minur	08	Conditor Districts
		Land 1990 Support CONSIGNAL SCARAGE Res Prog		
		Laws 1 Male Repaired Charlenge P. Law Res. Mater	CK Industry	
	Caller Caller	Lovel 1 SNN: Comprese Child Chiler 3- Low New Compressor Network	08	
		Loss 1 MMC Represent Child Chile 1- Los Rise Meter	OK. Ted same	
		Lover 1 Mark Experience, CARP of ARP 201235 Sec. Children Purg 1, Monte Lover 1 Mark Discovery CARP 1, 4000 Million Ave. (Links Mark Purg 1, Monte Lover 1 Mark Purg 1, Monte Lover 1 Mark Purg 1, Monte Lover 1, Mark Purg 1, Mark Purg 1, Monte Lover 1, Mark Purg 1, Monte Lover 1, Mark Purg 1,		
		Love 1 Mark replaced Color in Adjusted Section 2010 Section 2010		
		Lovel 1 MMC Epoposetti CMMP III Sex CMInd Meter Pure 1: Pure		
		Lover 1 Mills (Apopnent (1985) of dill(10)(1) Sec (Island More Pump). More	08	
		Land 1996 Despects Crittle 16 AM-20101 Au Chine Max Party 2 Party	-04	
	baue malary			
	a boots IN	February (FPC)	No. OF	_

Figure 1: Vibration Analysis Data Platform

Among the problems identified through condition monitoring included motor bearing outer race fluting, pulley misalignment, a buildup of matter on fan impellers affecting balance and efficiency, low grease levels on bearings, and the condition level of pump impellers.

"Having vibration analysis data at our disposal in order to pin-point faults efficiently allows us to make precise decisions when recommending repairs and directing maintenance personal efficiently, often avoiding labour intensive disassembly and inspection," said Sean O'Shaughnessy, Account Manager for Airmaster.

In one example, high levels of vibration were measured on the AHU 5 fan shaft bearing. By identifying that the vibration was a result of a build-up of matter on the fan impeller, the impeller was pressure cleaned and excessive vibration eliminated, avoiding labour-intensive disassembly & inspection along with the potential need to replace the bearings and perform a dynamic balance.

The reduction in vibration is displayed in Figure 2.

In another example, the program predicted the failure of a 75 kW supply air fan motor, in turn avoiding the large cost of repair.

"Using a real-world example from another building demonstrates that had predictive maintenance not been in operation, repair costs would have been up to \$32,000, with the works resulting in ten days of equipment downtime," said Graham. "Instead,

Pre Fan impeller cleaning overall velocity readings 10.5.17.	Post Fan Impeller Cleaning overall velocity readings 2.8.17.
Fan DE vertical: 3.3mm/s RMS	Fan DE vertical: 3.1mm/s RMS
Fan NDE vertical: 3.9mm/s RMS	Fan NDE vertical: 2.9mm/s RMS
Fault Condition Rating: *** Severe	Fault Condition Rating: OK; no problems are indicated.
Potential cost of total failure \$ 8,000 and ten days downtime Without V.A insights the cost to replace bearings and dynamic balance \$ 4,500 and three days downtime would have been realised	With V.A data we could confidently undertake these repairs that cost \$ 1,100 and resulted in no equipment downtime.

Figure 2: Excerpt from May & August Vibration Analysis report

repairs were undertaken at a cost of just \$2,374. No downtime was encountered, and tenants were not affected by the maintenance activities."

Streamlining Maintenance through Bonfire

The BUENO Bonfire platform facilitates the prompt and free-flowing resolution of issues by broadcasting and tracking progress of all issues from discovery through to resolution.

Bonfire allows multiple stakeholders to provide input into any issue and collaborate to solve problems. Any team member is able to log in and check the progress of an issue or communicate to resolve with others in the team.

tiset burnney Column. Column. Column.						have Detel	Contenents		
#Leperts-Ok					Santh			BVEND	ar 110, 128 Pp
8	Priority	homey	Site	Responsible	Updated -	Status	Contract	to check logic before AM verifies.	
								Attachments	
89-271	Oritical	Crucial equip in fault or dorm	222 Exhibition 52	Mech. Contraction	Jul 1895, 12:04 PM	To Be Raced Mild	Maintenance		
45-342	Major	Knight hank. Crucial unit-narring after hours: Schedule changed	312 Exhibition St	Site Local	jui 180, 11.59 AM	Packed	Maintenance	JCI Technician	No. 22-9, 1938-00
47.735	Major	Unexpected value: 27 seasor failed	222 Exhibition St	BMS Contractor	Jul 1815, 11:34 AM	To the Railord Mild	Buistmoner	tried to auto-calibrate all the Boxet I	thad. None where able
825-2981	Critical	snight hank sho starved while SNI pressure at man	222 Exhibition St.	Mich. Contraction	(si 1025.218 AM	To be Raised Mid	Maintenance	to dose completely and it. All to the	a toay
87-433	Critical	sits lealing while scoupled	222 Exhibition 51	Mech. Contractor	Jul 1005, 218 AM	To the Raised MM	Maintenance	ATA Trachesisters	Page Lines 10.00 core
82-785	Critical	Knight hank: Cruckel equip in fault or alarm	222 Exhibition St.	Mitch, Contractor	[611305.218 AM	in Review	Maintenance	2.7 1011010	
87-432	Critical	Kright frank Equip not running while condition	222 Exhibition St.	BMS CORENTIAL	pair19/5, 218 AM	To the Raised MW	Maintenance	AM	
82-610	Major	Kright hark, byly off while ond on	222 Exhibition St	BMS Contractor	(411) 2.18 AM	To be Raised Mid	Maintenance		No. 120, 1218-00
82-711	Critical	Active Capacity lients on Chillers	222 Exhibition St	Mitch, Costractor	painters, 2 se AM	To die Raised MM	Maintenance	BUENO	
65-728	Major	VSD speed fixed	222 Exhibition St.	BM6 Contractor	pai 1305, 218 AM	To the Randed Mind	truinterunce	AM & (C) to check together next shift	
Showing rown t	to 18-of 52					1 2 3	4 5	ARRANTER Technician	age 2001, 12:10 PW
								analyze most of these are parallel a	1000010000000
								ARRADICE Technician	140-00.12 (0.7%
								Migsically checked out loan/garanted to faults with 16.21, damper position access to constrainty 16.24 found damp to adjusted damper and re-strained chores. Collisioned each box via DMC	en ansist) 16.21/16.34. Nally closed at UN-(poor ee nut/fully closed at confirming/it non-fully

Figure 3: Bonfire Workflow Platform

To measure the effectiveness and in order to proactively adjust the maintenance program accordingly, tenant comfort, along with energy use, water use and condition monitoring data is displayed live using the BUENO dashboard.



Figure 4: Thermal Comfort Tracking



Tangible savings

Since the implementation of the predictive maintenance program in September 2016, electrical energy consumption has fallen by 15.5% on the previous year. This has been achieved despite a 13% increase in occupancy.

Even after regression modeling has been used to correct the figures for weather, the saving is still 11.5%, or 260,141kWh.



Figure 5: Energy like day analysis dashboard.

These savings can be attributed to a number of issues being identified and resolved including faulty temperature sensors generating false heating and cooling calls and broken or out of calibration Variable Air Volume dampers leading to excess or restricted flow causing upstream fans to ramp up. After-hours operation of AHUs was also addressed, which eliminated fan energy waste and reduced chiller, boilers, and associated pumps, being called on after-hours.

The property's NABERS Energy rating has also improved from 3.5 stars in 2015 to 4 stars.

Subsequent to the success achieved at 222 Exhibition Street, Airmaster will now look to offer predictive and data-driven maintenance as a highly recommended option to their clients.

"The use of data that is readily available within a building to develop entirely new ways of providing service and maintenance will disrupt the building services industry in unprecedented ways," said Noel Courtney, CEO of Airmaster Australia.

"With sophisticated data analytics and corresponding processes that streamline maintenance and reactive service calls, a new hybrid service option has been created. Optimisation techniques generated through the analytics process just add to the overall value proposition. This creates higher value services for our customers."

About Us //

Airmaster is an award-winning technical solutions company, delivering end-to-end management of heating, ventilation,air conditioning, industrial and process cooling and building automation across Australia and South East Asia. Based in Melbourne and with 15 branches Australia-wide, Airmaster's commitment to sustainability is achieved through a proactive, integrated approach to helping organisations achieve energy efficiency in innovative ways.

www.airmaster.com.au 1300 247 627

